## 300 270 Step 1: 2 fix the sorew on the cross. 240 104, 8 -74, 8 1) fix the M6 sorew on the ceiling. ix the cross on the M6 screw. \$25\*L490-1pcs \$25\*L550-1pcs \$25\*L610-1pcs \$25\*L670-1pcs \$25\*L730-1pcs \$25\*L730-1pcs \$25\*L430-lpcs 10 Step 2: N 2) fix the baseplate on the ceiling. Θ 14PCS Connect the pewer 0 14PCS

## NM2138--1E

Use the gloves provided to ensure the light fitting is not marked during installation.

Ensure the location chosen is suitable for the light fitting.

Ensure that the power is off where the light fitting is to be installed, to prevent electric shocks.

Ensure the power is isolated when cleaning or maintaining the fitting. Use non-corrosive detergent for cleaning.

When connecting to power cables, ensure the terminal stude are secure.

